

QIT-X



Supplier applied
capacity label

⚠ WARNING

Material handling is inherently dangerous. Improper use of this trolley might result in operator and/or bystander death or serious personal injury.

- Maximum rated load of trolley MUST equal maximum rated load of crane;
- DO NOT exceed maximum rated load of trolley, crane, hoist, or below-the-hook lifting device **whichever is smallest**;
- AT LEAST once per month, verify all 4 rollers make substantial contact with beam flange. Adjust threaded load bearing islet if necessary.

1149

1149

Applied on the opposite side of the
capacity label

Label 1072 is to be applied to the
outside of individual packaging

⚠ WARNING:
Reproductive Harm -
www.P65Warnings.ca.gov.

⚠ ADVERTENCIA:
Daño Reproductivo -
www.P65Warnings.ca.gov.

1072

⚠ WARNING: Cancer -
www.P65Warnings.ca.gov.

⚠ ADVERTENCIA: Cáncer -
www.P65Warnings.ca.gov.

MANUAL TROLLEY

9/17/20