

FTDC-6-4400


A = Label 1128

B = Label 1129

1. Determine where clamps (A) should be located on forks.
2. Slide clamps onto forks with shackles on top.
3. Loosen or tighten clamp bolts as necessary to adjust clamp locations. Tighten bolts when clamps properly located.
4. Engage load with forks.
5. Slide brackets (B) onto forks. Brackets have large holes and small holes. Forks go in large holes. Small holes must be on top.
6. Attach rigging to shackle of clamp and small hole of bracket.

1106

Tag 1106, attached by zip tie



Label 1072 is to be applied to the outside of individual packaging

WARNING:
Reproductive Harm -
www.P65Warnings.ca.gov

ADVERTENCIA:
Daño Reproductivo -
www.P65Warnings.ca.gov

1072

WARNING: Cancer -
www.P65Warnings.ca.gov

ADVERTENCIA: Cáncer -
www.P65Warnings.ca.gov

FORKLIFT TIE DOWN CLAMPS

5/21/20