

HPC-405

ISO 32 / 150 SUS

HYDRAULIC OIL OR NON-SYNTHETIC TRANSMISSION FLUID
ACEITE HIDRAULICO O LIQUIDOS DE TRANSMISION NO SINTETICOS
HUILE OU LIQUIDE HYDRAULIQUE NON-SYNTHETIQUE

206, By Oil Fill



⚠ DANGER	ELECTRICAL SHOCK Shut power off and consult owners manual before working on this equipment.
⚠ PELIGRO	EI GOLPE ELECTRICO Corte la corriente consulte el manual de propietario antes de trabajar en este equipo.
⚠ DANGER	CHOC ELECTRIQUE Couper le courant et consulter le manuel d'utilisation avant de travailler sur cet équipement

221, On Door

NOTICE	NOTA	AVIS
POWER SUPPLY: 115V/1 Phase/60 HZ CONTROL VOLTAGE: 24V AC CORRIENTE: 115Volt/1 Fase/60 HZ VOLTAJE DE CONTROL: 24V CA ALIMENTATION ELECTRIQUE: 115V/1 Monophase/ 60HZ VOLTAGE DE CONTRÔLE: 24V AC		

On Door, 248 - 251

⚠ WARNING
LOCK LOADING DOOR before operation DO NOT OPERATE if door lock is broken KEEP AWAY during operation Operation by trained personnel only
⚠ ATENCIÓN
LOCK LOADING DOOR before operation DO NOT OPERATE if door lock is broken KEEP AWAY during operation Operation by trained personnel only
⚠ ATTENTION
LOCK LOADING DOOR before operation DO NOT OPERATE if door lock is broken KEEP AWAY during operation Operation by trained personnel only
Vestil Manufacturing Corporation Phone: (260) 665-7586 • www.vestil.com

300

⚠ WARNING	⚠ ADVERTENCIA	⚠ AVERTISSEMENT
SECURE FRAME TO FLOOR	ASEGURE EL BASTIDOR AL PISO	FIXER SOLIDEMENT LE CADRE AU PLANCHER

204, On Each Leg

⚠ WARNING	⚠ ADVERTENCIA	⚠ AVERTISSEMENT
KEEP CLEAR WHEN IN USE	MANTENGASE ALEJADO CUANDO SE ESTA OPERANDO	SE TENIR À DISTANCE LORS DU FONCTIONNEMENT

220, Each Side

Label 1072 is to be applied to the outside of individual packaging

⚠ WARNING: Reproductive Harm - www.P65Warnings.ca.gov.	⚠ ADVERTENCIA: Daño Reproductivo - www.P65Warnings.ca.gov.
⚠ WARNING: Cancer - www.P65Warnings.ca.gov.	⚠ ADVERTENCIA: Cáncer - www.P65Warnings.ca.gov.

PAIL CRUSHER / COMPACTOR

6-20-2022